


Operating instructions

METTLER TOLEDO AM/PM Balances



METTLER TOLEDO

Thank you very much for the confidence you have shown in our products by choosing a METTLER TOLEDO precision or analytical balance. To obtain complete satisfaction from your balance, it is essential that you read through these operating instructions carefully.



These operating instructions apply to balances of the AM and PM series with a weighing range up to 6 kg. Although the operating procedures for these balances are identical, differences exist regarding the weighing range, the readability accuracy and the weighing pan or platform.

Enclosed with these operating instructions is the booklet «Technical data and accessories», which also contains possibilities of the METTLER TOLEDO AM/PM balances.

		Page
Preparation	Choosing the location	4
	Mounting the weighing pan / levelling the balance	5
	Installing the draft shield	6
Operation	Control elements / connections / display	8
	METTLER DeltaTrac / METTLER DeltaRange	9
	Switching display on and off	10
	Simple weighing / taring	11
	Single-key (control bar) operation	12
Menu	Overview	14
	Calibrating	15
	Adapting to the type of weighing (weighing process adapter)	16
	Adapting to the ambient conditions (vibration adapter)	17
Configuring	Overview	18
	Configuration example	20
	Standard settings and record printout	22
	Balance operating settings	24
	Unit selection, applications, print / transfer command, status display	26
	Adapting to external equipment	28
	Protecting the configuration	30
Applications	Overview	32
	Switching the weight unit	33
	Piece counting	34
	Plus / minus and percent weighing	36
	Animal weighing	38
	Print / transfer command	39
What if...	Fault rectification	40
Miscellaneous	Changing the operating voltage / replacing the fuse	42
	Changing the protective cover / maintenance	43
	Technicals terms	44
Technical data	Overview	45



Select the proper location

For best results choose a suitable location for your balance.



A firm, vibration-free location as horizontal as possible

Avoid exposure to direct sunlight




No extreme temperature changes

No draft

Despite a possible unfavorable location, your balance can still produce accurate weighing results:


In this case you should adjust the vibration adapter accordingly. For procedures refer to section «Menu».

Mount the weighing pan / platform



PM balances with weighing pan

Place pan support **11** and weighing pan **10** on tapered pin **17**; connect power cable **20**.




PM balances with weighing platform

Install platform support **11** with the four pins resting on the four rubber grommets **40**; then position weighing platform **10** on platform support **11**; connect power cable **20**.

AM balances: see page 7.

...and now, level the balance




After each relocation of the balance, repeat levelling procedures. For this purpose adjust bubble in level indicator **9** with the two levelling screws **8**.

Preparation

Don't forget to install the draft shield


To ensure that the weighing results are not influenced by the drafts (particularly for sensitive measuring ranges) we recommend the installation of a draft shield.




PM balances with 1 mg readability

Mounting procedures 1 and 2 are needed only if the bottom element 12 has not been installed at the factory.


Remove weighing pan 10 and pan support 11.



Place bottom element 12 on balance, and rotate to stop. Replace pan support 11 and weighing pan 10.




Mount draft shield 13 and engage.




AM balances

Mount glass draft shield **13** on scale rotated by 45°. Note that tapered pin **17** must be visible through bottom hole **27**. Now rotate glass draft shield clockwise to stop.




Verify that the draft shield is aligned parallel to the balance and is properly engaged in bayonet base.



Install ring **25** and weighing pan **10**, close sliding door **26**.


Note: Ring **25** protects the weighing pan from lateral impacts.

Control elements and connections



- 1 Control bar
- 2 Program cassette
- 3 Cover
- 4 Connector for data interface
- 5 Connector for METTLER TOLEDO GM instruments
- 6 Fuse holder (with spare fuse)
- 7 Power socket
- 8 Screw feet (level adjustment)
- 9 Level indicator

Display




- 31 Status indicator
- 31a Vibration adapter
- 31b Weighing process adapter
- 31c Weight status
- 31d Automatic zero correction (Autozero)
- 31e Special status of digital display ¹⁾
- 31f Stability control
- 32 Digital display
- 33 Units
- 34 METTLER DeltaTrac (dynamic graphic indicator and dispensing aid with 60 radial segments)
- 35 Tolerance limits


¹⁾ indicates calculated quantities such as mean values or values multiplied by constants, as well as data entered via the interface

The METTLER DeltaTrac

This **dynamic graphic indicator** with 60 radial segments is incorporated in all balance models. METTLER DeltaTrac shows you a **graphic** representation of the numerical values shown in the digital display.



With absolute weighing, subtractive weighing, weighing-in and formula weighing, the dynamic display indicates the **weighing range used up and that still remaining**.




With the aid of METTLER DeltaTrac you can check fill quantities and determine deviations from a definable target weight in percent.

You can always see **the tolerance limits** with correct signs, as well as positive or negative deviations (see «Applications»).

When used together with METTLER TOLEDO Pacs, the METTLER DeltaTrac can also perform additional functions (see booklet «Technical data and accessories»).

METTLER DeltaRange® balances...


...include a fine range with **10 times the normal accuracy**. Briefly pressing the control bar (taring) will activate DeltaRange anywhere throughout the entire weighing range.



Note: You also have the 10 times more accurate fine range available in subtractive weighing.

Operation

Switch on display (▼ Display changes automatically)



Display switched off (standby)

Briefly press controll bar; all display segments light up briefly (automatic system and display check).

Software No. (e.g. 10.40.00, for information only).

Display subsequently indicates zero (weighing mode). The number of decimal places depends on the readability of your balance model as well as the selected weight unit.

Note: If a power outage occurs during operation, the display will indicate OFF immediately the power is restored. You should then briefly press the control bar (also consult «What if...»).

Switch off display



Weighing mode

Lifting the control bar from below causes the display to blank out; the electronics are live as long as the power cable is connected (Standby). The balance is thus always ready for operation; no warm-up time required.

Simple weighing

Caution: Before the balance is used for the first time, it must be calibrated (see «Calibration» in section «Menu»).




0.00_g

Weighing mode



118203_g

Load weighing sample



125000_g

Wait for stability and read result
(Stability is reached as soon as stability detector fades).

Taring (▼ display changes automatically)




0.00_g

Weighing mode



121.01_g

Load an empty container or packing.



— — — — —_g

Brief pressing of control bar initiates taring cycle.

▼
0.00_g

The container or packing has now been tared.
The weighing range minus tare weight is now available for weighing-in.

Note: The stability detector can be switched off during taring by pressing the control bar twice. It is then possible that the display does not show exactly 0.00 g. The foot or hand switch from the accessories offers the possibility of external taring (connection at rear of balance).


Simple operation with a control bar

Switching on/off, calibrating, configuring: All of these operations can be initiated with the control bar. You can even use this single control bar to activate the applications incorporated as standard.


For more convenient operation of the applications, the GM303 Terminal (direct function, switch and print key) from the accessories can be used.

Note these symbols...


...You will find them throughout the operating instructions and short-form instructions.



Press
control bar
briefly



Press and hold
control bar
until required display appears



Display changes
automatically

Introducing the symbols

Try to familiarize yourself with the key symbols with the aid of the following example. Switch on the display and remove weight from weighing pan. Now try to select and change the weighing process adapter **31b**.




Note: If the display automatically returns to zero (weighing mode) 3 seconds after the control bar was last pressed, simply begin the procedure again.

Have you adjusted the status display so that the «drop symbol» is shown on the left of the display? If your first attempt was unsuccessful, try again. You will find further information regarding the weighing process adapter and much more in the following sections.

A clear Menu

We distinguish between two levels of software. The first, simpler level, we call the **Menu**. It can be activated by pressing and holding the control bar. The second software level is called the **Configuration** file. Details can be found in section «Configuring».

When the Menu is activated, you can...



...**calibrate** your balance,

...use the **weighing process** adapter to set the weighing modes or the weighing sample, and

...use the **vibration adapter** to adapt the balance to the ambient conditions.

You can select the menu from the weighing mode. Switch on display and remove load from weighing pan. Then press control bar (and keep depressed): The menu sequence starts. After the third menu step the balance returns to the weighing mode. Now release the control bar.

Note: If you have selected the menu step «Weighing process adapter» or «Vibration adapter» and do **not** press the control bar for **3 seconds**, your balance will return automatically to the weighing mode. However, the actual settings are stored (the same applies if you return to the weighing mode by pressing and holding the control bar).

-CAL-

Calibrate your balance

Before the balance is used for the first time, it must be calibrated (to take the acceleration due to gravity into account).

Caution: To obtain accurate results we recommend that you connect the balance to the line 30 min before calibrating (60 min for AM balances).



Start calibration with display switched on by pressing and holding the control bar (weighing mode, display zero with empty weighing pan).



Release control bar as soon as -CAL- appears in display.



Required calibration weight, e.g. 1000.00 g, flashes.



Place required calibration weight on balance.



Prompt to remove weight.



Remove weight from balance.



The balance is recalibrated, (it is now back in weighing mode).

Adapt your balance to the type of weighing (Weighing process adapter)...

Access



Weighing mode




Weighing process adapter

Adjustments

Weighing process

Remarks



Fine dispensing (weighing-in) of fine powder or small quantities of liquids

For **slow filling-in** of weighing goods **all decimal places** of the display are available. The weight increase can thus be followed easier.

Universal

Standard setting. With DeltaDisplay –on–, the last decimal place is suppressed in coarse dispensing, see page 25.

Absolute weighing

In this setting, you can **rapidly check a weight**. Only the final result appears in the display. «-----» is displayed during the unstable phase.

Animal weighing

Your balance is now operating in the **animal weighing mode**, e.g. movements of a live animal do not influence the display. The measurement values are averaged during a certain time period and subsequently indicated on the display.

Starting of measuring cycles and setting of measuring time are explained in section «Applications, animal weighing».



...as well as to the ambient conditions (Vibration adapter)

Access



Weighing mode




Vibration adapter

Under vibration-free conditions adjust the adapter to obtain results within the shortest possible time. However, if you are operating in an environment with severe vibrations or drafts, adjust the adapter to obtain reliable results, even under adverse conditions.

Adjustments

Weighing environment

Remarks



Very quiet and stable

Whit this setting your balance operates **very fast** (short weighing cycle), but the balance is relatively sensitive to ambient disturbances.

Normal

Standard setting

Unstable, e.g. draft or strong building vibrations

Your balance is **not sensitive** to external disturbances, however, its operation is slowed down.

Special requirements need special settings within the configuration file

Your balance has been factory-set to a standard configuration, i.e. the settings in the configuration file correspond to the most common user requirements. If you wish to change these settings to meet special requirements you must access the configuration file and change the settings according to your needs. The configuration file is divided into four sectors, in which you can change the following settings:



Standard setting and record printout



Resetting to standard configuration



Printout of balance specification values and actual configuration (printer connected)



Setting balance operating parameters



Changing stability detector (four settings)



Reducing readability



Switching off METTLER DeltaDisplay



Switching off automatic zero correction



Unit selection, applications, etc.



Selection of basic unit



Selection of second unit and applications



Print/transfer command / Starting animal weighing mode



Switch on status displays



Adapting to peripheral units



Transmission mode



Baud rate



Parity




Pause between data transfers and handshake

Please see the following pages for more information on the individual setting possibilities.

Note: Short-form operating instructions are enclosed with this operating manual and show the configuration file with all possible settings. These short-form instructions are intended for use as an overview aid in your day-to-day work.

Configuring – a quick introduction




Access

Start from standby, i.e. display switched off.

Now, press control bar and **release only** when display shows –Conf.–.

Display now automatically changes over to –Reset–.



Selecting sectors

The 4 sectors can be selected by **briefly** pressing the control bar.

Note:

The –End– display between the sectors –I-Face– and –Reset– indicates the end of the four sectors.



Selecting adjustment


For instance in sector –Unit–:

Keep control bar **depressed** until the desired selection is displayed (e.g. –Unit 1–).

Have you found the setting –Unit 1–? If not, switch off the display by lifting the control bar. Then restart by accessing the configuration file. This time it's sure to work.



Press briefly x times



Change setting,

e.g. from –g– (gram) to –ct– (carat):

Briefly press control bar several times until carat (ct) appears in display.



Return to weighing mode

After completing your configuration keep control bar **depressed** until zero indication appears (weighing mode). The effective settings are now stored, and you can proceed with your weighings.


Note: If you release the control bar **at –End–** (each sector is terminated with –End–) and then **press briefly**, you will return to the start of the corresponding sector (e.g. –Unit–).

If, after making these changes, you would like to return to the **standard configuration**, please turn to the next page. The following pages also tell you everything you wish to know regarding the individual setting options. A general overview of the configuration file is available from the enclosed **short-form operating instructions**.

rESEt


Standard setting and record printout

Access




Standby


Symbols



Press
control bar
briefly



Press and hold
control bar
until required display appears




Display changes automatically

Important

Return to weighing mode by **keeping control bar depressed** until zero indication appears.

If you do not press control bar for **40 sec**, the balance will **automatically** return to weighing mode.



Settings

Standard setting Yes / No

For resetting your balance to standard configuration, select sector –reset–. Now press control bar until –yes– is displayed. **By pressing and holding the control bar again until –End– or zero appears, you acknowledge** the resetting (weighing mode appears after –End– indication). Your balance is now reset to the original factory setting.

Printout of balance specifications and the actual configuration Yes / No?

To obtain a printout of balance specifications and the selected settings in the configuration file, select –ON–. **Acknowledge** the List command by pressing and holding the control bar until – – – – – appears. The record with the following values can be printed out with an attached printer (e.g. METTLER TOLEDO GA44):

Balance specification values

- STANDARD Software version, e.g. V.10.40.00
- TYPE Stock designation, e.g. PM2000
- INR Identification No., 7 digits
- FULL Weighing range, e.g. 2100.90 g
- d Readability, e.g. 0.01 g
- CAL Calibration weight value


Actual configuration

- ASD Stability control, e.g. step 2
- d Readability, e.g. 0.01 g
- dd Delta Display, e.g. on
- AZ Automatic zero correction, e.g. on
- Unit 1 Basic unit, e.g. g
- Unit 2 Second unit, e.g. g or applications e.g. pcs
- Prt Print/transfer command, e.g. off
- [] [] Status display, e.g. auto
- S Transmission mode, e.g. Stb
- b Baud rate, e.g. 2400 baud
- P Parity, e.g. –E–
- PAUSE Pause duration between data transfer, e.g. 1 s
- AU Suppress special characters, e.g. on


SCALE

Setting balance operating parameters


Access



Symbols



Press
control bar
briefly



Press and hold
control bar
until required display appears



Display changes automatically



Standard setting




Selectable setting

Important

Return to weighing mode, **always** with control bar depressed till zero indication.

If you do not press control bar for **40 sec**, the balance will **automatically** return to weighing mode. Modified settings will be recorded.



Settings

Automatic stability detection

The stability detector 31f lights up when the balance is unstable. At the same time, the data interface is blocked until the weighing result is stable (except for data transfer mode «S» being set to –All– or –Cont–; see sector –I-Face–).

☐ -1-

Weighing speed:

very fast

Reproduction:

good

☒ -2-



fast

☐ -3-



very good

☐ -4-

Selection of display sequences (Readability)

Example for 0.1-g balances:

Step	(d)	1	2	5	10	20	50	100
Display	(g)	<input checked="" type="checkbox"/> 0.1	<input type="checkbox"/> 0.2	<input type="checkbox"/> 0.5	<input type="checkbox"/> 1	<input type="checkbox"/> 2	<input type="checkbox"/> 5	<input type="checkbox"/> 10

Weighing-in aid (DeltaDisplay) switching on or off

The DeltaDisplay is a weighing-in aid for fast and accurate weighing-in. Decimal places are reduced by one as a function of weighing-in speed. During the final phase of the weighing-in process the balance automatically switches over to normal weighing:

☒ on

switch on

☐ off

switch off

Automatic zero correction (Autozero) switching on or off

Autozero automatically compensates for zero drift or soiled pan.

☒ on

switch on

☐ off


switch off

Note: The symbol –AZ–, in either position (on/off), appears only in the configuration file.

Unit


Unit selection, Applications, Print/Transfer command, Status display

Access




Standby

Symbols



Press
control bar
briefly



Press and hold
control bar
until required display appears



Display changes automatically



Standard setting




Selectable setting

Important

Return to weighing mode **always** with control bar depressed until zero indication.

If you do not press control bar for **40 sec**, the balance will **automatically** return to weighing mode. Modified settings will be stored.



Setting options

Basic weighing unit

In addition to the weight unit g, the following weight units can be selected for weighing:

☒ g gram ☐ kg kilogram ☐ lb pound ☐ oz ounces ☐ ozt troy ounces ☐ tl tael ☐ GN grain
☐ dwt pennyweight ☐ ct ☐ C.M. ☐ k carat ☐ no unit display (display value in g)

Note: The number of decimal places depends on the balance model and selected weight unit (see «Decimal places for secondary units» in the booklet «Technical data and accessories» and «Conversion factors» in the section «Applications» under «Switching weight unit»).

Switchable second unit

–Unit 2– includes the same weight units as basic unit. In addition you may select:

☐ PCS ☐ Stk Piece counting ☐ % Plus/minus or percent weighing

For further information regarding these applications, see section «Applications».

Switch print / transfer command on or off

Print of the indicated weight value or initiation of transfer command with control bar.

☒ OFF switch off ☐ ON switch on

If operating in animal weighing mode, you can initiate a new measuring cycle with the control bar. For additional information see section «Applications».


Switch status indicator on or off

☒ AUTO 3 minutes after switching on balance, the two status indicators fade automatically ☐ ON Auto: The two status indicators remain active, i.e. they are always visible on display.


1 - FACE

Adaptation to external equipment


Access




Symbols



Press
control bar
briefly



Press and hold
control bar
until required display appears



Display changes automatically



Standard setting



Selectable setting

Important

Always return to weighing mode by keeping control bar depressed until zero indication appears.


If you do not press control bar for **40 sec**, the balance will **automatically** return to weighing mode. Changed setting will be stored.

General information

All METTLER TOLEDO precision or analytical balances are factory-equipped with a bidirectional interface (CL and RS232C). For detailed information see operating instructions «Bidirectional Interfaces for PM balances». (See also «Miscellaneous, Auxiliary equipment»).

Data format of balance interface:

1 start bit, 7 data bit, 1 parity bit, stop bit automatic (1 RX / 2 TX)



Setting options

Datenübertragungsmodus

Stb

The next possible stable value is transferred after initiation of print/transfer command (after release by stability detector).

ALL

The current value (dynamic «SD» or stable «S») is transferred after initiation of print/transfer command.

Auto

Only stable values are transferred after every change of weight (necessary change 1 g. Exceptions: PM6: 5 g and AM50/AM100: 0.2 g. For animal weighing see section «Applications»).

Cont

All values (dynamic «SD» and stable «S») are transferred automatically.

Baud rate

The baud rate is the transfer rate unit for serial data transmission in bit/sec:

110

150

300

600

1200

2400

4800

9600

Parity

Parity control permits recognition of simple bit errors in data transmission:

-E-

even parity

-O-

odd parity

-M-

mark parity

-S-

space

Pause between transfers and handshake (hardware related for RS232C)

Settings –Pause 0–, 1 and 2 permit the adaptation of transfer rate to data receivers working at different rates (specifications in seconds). –Pause H– evaluates the hardware related handshake signal for RS232C. The balance is ready for handshake mode operation.


Caution: For handshake mode operation the transfer input may not be used.

Certification symbol in data transmission


If balances are connected to peripheral units that can not process the certification symbol (<...>, *) (e.g.LP16-M Infrared Dryer and SQC systems) or if a printout of these characters is not required, the function –Au– must be set to –on–.

How to protect the new settings in the configuration file


After having completed your configuration, you can protect your settings against inadvertent changes. Proceed as follows:




To protect the program cassette from possible interface, it is absolutely essential to first disconnect the line cable **20**.




Now remove cover **3**, for instance with a screwdriver. The program cassette is now visible.




Grasp bracket of program cassette **2**, and carefully pull out cassette.



In the aperture of the program cassette **2**, the shorting jumper **24** is now visible. It can be lifted off from the contact pins (e.g. with a small pencil).



To protect your settings in the configuration file from involuntary changes, position the jumper across **both** contact pins (position **secured**).



Reinsert the program cassette **2**. Ensure that you push it in firmly right to the stop. Then press on the protective cover **3**. Connect power cable **20**.

Your settings are now secured, i.e. accessing the configuration file is no longer possible. If you wish to remove the security provision, follow the sequences shown in Figures 1 to 4. In Figure 5 select the position «**not secured**».

Standard applications at a keystroke

Counting in or out of a container, percent formula weighing of powders or liquids, plus/minus checks of fill quantities, weighing in grams or in a second, selectable unit, or even animal weighing: all this and more can be performed with the applications built in as standard. You can choose between the following applications:



Changing weight units

You can switch between two selected weight units, e.g. between gram and carat.



Animal weighing

Animal weighings can also be performed simply and rapidly.



Piece counting

The balance can be used for piece counting; 10 is the fixed reference value.



Print/transfer command


Print/transfer command can be initiated with the control bar.




Plus/minus and percent weighing

The balance can also be used for plus/minus checks. If your balance is used for checks in %, the METTLER DeltaTrac indicates the deviation from the preset target weight, the tolerance limits of +/- 2,5 % and their violations. You can of course perform the usual percent weighings simply and rapidly.

Symbols



Press control bar **briefly**




Press and hold control bar until required display appears




Display changes automatically

Switching weight unit

Configuration



Working with two units



Conversion factors

ounce	1 oz ≈	28.349523125 g	1g ≈	0.035273962 oz
pound	1 lb ≈	453.59237 g	1g ≈	0.002204623 lb
pennyweight	1 dwt ≈	1.55517384 g	1g ≈	0.643014931 dwt
troy ounce	1 ozt ≈	31.1034768 g	1g ≈	0.032150747 ozt
grain	1 GN ≈	0.0647989 g	1g ≈	15.43235835 GN
carat	1 ct =	0.2 g	1g =	5 ct
tael	1tl ≈	37.4290 g	1g ≈	0.026717213 tl

175 PCS




Piece counting (fixed reference number – 10 pieces, 1 item at least 1/4 digit)

Configuration




Standby



Select –Unit 2– in sector –Unit– of configuration file



Press briefly x times




Now changes this setting to –PCS–
(piece counting is now effective)




Return to weighing mode


Counting into a container





Place empty container onto
balance, tare



Add 10 items to container (to
obtain reference)




Press control bar until
–SEt 10 PCS– appears
(reference will be stored)



Add quantity to be
determined


Switch piece count/weight readout



Return to weighing mode


Select piece counting

Counting out of a container




0.00 g

Place filled container on balance, tare



-65.87 g

Remove 10 items (reference)




till

SEt 10 PCS

Press control bar unit –SEt 10 PCS– appears (reference is stored)

- 10 PCS



- 175 PCS

Take out quantity to be determined


%

Plus/minus and percent weighing (tolerance limit $\pm 2,5\%$, 100 % = target weight, min. weight = 100 digit)


Configuration




Standby




Select –Unit 2– in sector –Unit– of configuration file



Press briefly x times




Now changes this setting to –%– by briefly pressing control bar (plus/minus or percent weighing is now effective)




Return to weighing mode

Set target weight




Place target weight on pan



till





Press control bar until –SEt 100 %– appears (target weight will be stored)




Remove target weight

Checkweighing



Place weighing sample on pan and check if weight is within tolerance limits



Switch percent weighing/weighing mode




Number of decimal places as a function of reference weight

Reference (digit)	Display (%)	Display increments
< 100	—Err 3—	—
≥ 100	100	1
≥ 200	100.0	0.5
≥ 500	100.0	0.2
≥ 1000	100.0	0.1
≥ 10000	100.00	0.01
≥ 100000	100.000	0.01

Coarse weighing-in





Place empty container on balance, tare



coarse indicator

Add weighing sample rapidly; the coarse indicator moves downward (coarse indicator position six o'clock = target weight)

Fine weighing-in



fine indicator

Add weighing sample gradually; the fine indicator moves upward (fine indicator position 12 o'clock = target weight)

Target weight



When fine and coarse indicators from a vertical line, the target weight has been reached ($\pm 0,25\%$)



Animal weighing

Configuration



Set weighing process adapter **31b** to «Animal weighing»



Use vibration adapter **31a** to select the desired time cycle (integration time + reading time):



3 sec.



5 sec.



7 sec.

See also section «Operation».

The various displays have the following meanings



Balance ready for animal weighing



Weighing cycle in process
(integration time)



Read result (Available reading time:
Display remains stable for 3...5 sec)

Manual

- With the external transfer keys (see booklet «Technical data and accessories»)
- With the control bar of your balance (set print command to –Prt on–, see «print/transfer command» in this section):



Press control bar until –Start– appears.



When the control bar is released, the weighing cycle starts.

Note: If a printer is connected, the stable weight value is printed out automatically.

Automatic

- Set data transfer mode «S» to –Auto– (see also «Configuration, Sector –I-Face–»). Placing a live animal on the weighing pan automatically initiates a weighing cycle.




To initiate a new weighing sequence, the load on the balance between two animal weighings must be reduced to less than 2 g for 0.1 mg balances, 10 g for 0.1 mg/10 mg and 100 mg balances, 50 g for g-balances.

Note: For DeltaRange balances select smallest unit as a reference.

Configuration



Standby



Select –Prt off– in sector –Unit– of configuration file.

Now changes this setting to –Prt on– .
The print/transfer command or start command for animal weighing is now switched on.

Return to weighing mode.







Initiate print/transfer command










Press control bar until –Print– appears in the display. Weighing results are now printed out by an attached printer. Transfer commands may be initiated as well.




Note: If your weighing process adapter **31b** is set to «Animal weighing», the readout shows –Start– in place of –Print– (see also «Animal weighing» in this section).

A breakdown should occur anyhow

Display	Definition	Cause	Correction
	Display blank	<ul style="list-style-type: none"> - No Power - Scale switched off - Power cable disconnected - Temporary disturbance - Incorrect operating voltage - Line fuse defective - In case of repetition 	<ul style="list-style-type: none"> - Check power system; - Switch on scale - Connect power cable - Switch scale off/on, or pull out/plug in power cable - Correct voltage setting, see «Miscellaneous» - Replace fuse, see «Miscellaneous» - Inform METTLER TOLEDO Service
	Zero not defined	<ul style="list-style-type: none"> - Pan support or/and pan not in place 	<ul style="list-style-type: none"> - Place pan or/and pan support on balance
	Underload	<ul style="list-style-type: none"> - Pan support or/and pan not in place - Protective cover touching pan support - Lower limit of weighing range violated 	<ul style="list-style-type: none"> - Place pan or/and pan support on balance - Mount protective cover properly, see «Miscellaneous» - Tare
	Overload	<ul style="list-style-type: none"> - Upper limit of weighing range exceeded 	<ul style="list-style-type: none"> - Reduce load
	Power loss	<ul style="list-style-type: none"> - Power cable connected with display switched on - Temporary power failure 	<ul style="list-style-type: none"> - Tare - Check power connector is properly connected, then tare
	Weighing result unstable	<ul style="list-style-type: none"> - Unstable weighing location - Unsteady object on balance (e.g. animal) - Excessive draft - Incorrect operating voltage 	<ul style="list-style-type: none"> - Adjust vibration adapter, see «Operation» - Place scale on stable support - Set weighing process adapter to animal weighing mode, einstellen, see «Operation» - Install draft shield (standard accessory for AM balances and balances with 1 mg readability) - Correct voltage setting

Display	Definition	Cause	Correction
 	Incorrect result	<ul style="list-style-type: none"> - Operational error - Wrong unit - Protective cover touching pan support - Weighing sample touching housing or draft shield 	<ul style="list-style-type: none"> - Take off weight, tare and repeat weighing - Check levelling, see «Preparation» - Check calibration, see «Operation» - Select correct unit, see «Configuring» - Mount protective cover properly, see «Miscellaneous» - Rearrange weighing sample to avoid contact with housing or draft shield
	Unstable when taring, calibrating or setting reference	<ul style="list-style-type: none"> - Excessive draft or vibration - Stability detector setting too sensitive 	<ul style="list-style-type: none"> - Install draft shield (standard accessory for PM100. AM balances and balances with 1 mg readability) - Close sliding window (AM balances) - Adjust vibration adapter, see «Operation» - Adjust stability detector, see «Configuring»
	Taring in overload or underload condition	<ul style="list-style-type: none"> - See overload/underload 	
	Reference insufficient	<ul style="list-style-type: none"> - Reference is too small or missing (piece counting , plus/minus or % weighing) 	<ul style="list-style-type: none"> - Increase weight/ reference weight
 till 	Error message from internal electronics monitor during automatic self check	<ul style="list-style-type: none"> - Program cassette improperly inserted - Admissible temperature range exceeded 	<ul style="list-style-type: none"> - Insert program cassette correctly - Pull out/plug in power cable - If error message persists, contact METTLER TOLEDO Service

How to adjust the operating voltage




Make sure the power cable **20** is disconnected. With the power cable connected, the inside of the balance is live even if the display is blank! Lift off weighing pan **10** and pan support **11**; remove screw **21** and carefully lift off upper section of housing **22**. Reset voltage selector **23** with a screwdriver.

Carefully lower upper section of housing **22** vertically onto the balance. Replace screw **21** and tighten, place pan/platform support on tapered pin **17** or the four rubber grommets **40**. Finally, place the weighing pan or platform **10** on its support **11** and connect power cable **20**.

Caution: Change microfuse after changing operating voltage (see below).

Changing the microfuse – in a trice



The spare fuse is in the fuse holder **6**.

Fuse ratings: 115 V = 125 mA slow blow



230 V = 63 mA blow

Disconnect power cable. Lever out fuse holder **6** using a screwdriver. Remove blown fuse and insert a new one. Reinsert fuse holder **6**.

Reconnect power cable **20**.

Do not forget to order a new spare fuse.

How to change the protective cover



A soiled protective cover can be exchanged as follows: Lift off weighing pan **10** and pan holder **11**. For balances with round weighing pan, rotate bottom plate **12** or retaining ring **15** until disengaged, lift off. Position balance on its side. Remove control bar **1** by applying pressure toward **A**. It will disengage and can be lifted off in the direction of **B**. Remove protective cover **16**.


Installation of new protective cover for balances...

...with weighing pan

Fit new protective cover **16**. Slide on control bar **1**. Position bottom plate **12** or retaining ring **15** and rotate until engaged. Replace pan support **11** and weighing pan **10**.

...with weighing platform

Before mounting the new protective cover **16**, the two protective foils must be removed at the adhesion points. Next, to attach the new protective cover **16** at rear of balance and press down in front. Briefly press the two adhesive spots **41** against upper section of housing. Slide on control bar **1**, replace platform support **11** and weighing platform **10**.



Easy to clean




For cleaning the stainless steel pan, a cloth with soap and water is adequate. Never use powerful solvents.


Caution: Never position balance upside down (damage to measuring cell)!


You can't know all the words

Calibrating	Adapting the balance to a reference weight	LCD	Liquid crystal display
Configuration cycle	A run through the configuration file	Menu	The first level, consisting of calibration, adaptation of weighing process and vibration, can be extended with applications, see « Operation » and « Applications »
Configuration file	A second level, lockable with the jumper with variable parameters and selectable applications as additions to the menu, see «Configuring»	Reproducibility	The similarity of values obtained from repeated weighings on the same balance under the same conditions of measurement
Configuring	The setting of parameters, see «Configuring»	Sector	$\frac{1}{4}$ of the DeltaTrac, comprising 15 segments
Control bar	A single operating device for weighing, working through the menu and configuring your balance	Segment	A radial bar, $\frac{1}{60}$ th of the DeltaTrac
DeltaDisplay	An aid to fast, accurate weighing-in, see «Configuring»	Standard setting	The settings for normal user requirements
DeltaRange	Selectable fine range, see «Operation»	Standby	The balance is ready for use (power cable plugged in) but not switched on, i.e. display is blank
DeltaTrac	A dynamic graphic indicator with 60 radial segments, see «Operation»	Tare weight	The weight of weighing vessels or packaging
Digit (d)	The smallest displayed value (e.g. METTLER TOLEDO PM3000: 0.1 g)	Taring	Allowing for the tare weight(s), i.e. the digital readout shows zero
Dispensing	Precise weighing-in of powder or small amounts of liquid	Vibration adapter	A means of adapting the balance to its location, see «Operation»
Display	The entire display unit, see «Operation»	Weighing process adapter	A means of adapting the balance to the materials weighed, see «Operation»
FD	Fluorescent display		Weighing range, e.g. 2100.90 g
Indicators	These indicate the status of the balance, see «Operation»		Readability, e.g. 0.01 g
Jumper	A small connector for locking the configuration, see «Configuring»		Calibration weight value

Technical data for individual models



	AM50	AM100	PM100	PM200	PM400	PM1200	PM5003 Comparator	PM480 DeltaRange	PM2500 DeltaRange
Readability	0.1 mg	0.1 mg	0.001 g	0.001 g	0.001 g	0.001 g	0.001 g	0.01 g	0.01 g
- Fine range (recallable)	-	-	-	-	-	-	-	0.001 g	0.001 g
Weighing capacity	51 g	110 g	110 g	210 g	410 g	1200 g	5100 g	410 g	2100 g
- Fine range (recallable)	-	-	-	-	-	-	-	80 g	500 g
Taring range (by subtraction)	51 g	110 g	110 g	210 g	410 g	1200 g	5100 g	410 g	2100 g
Reproducibility (s)	0.1 mg	0.1 mg	0.5 mg	0.5 mg	0.001 g	0.001 g	0.0015 g	0.003 g	0.003 g
- Fine range	-	-	-	-	-	-	-	0.001 g	0.001 g
Linearity	± 0.2 mg	± 0.2 mg	± 0.002 g	± 0.002 g	± 0.002 g	± 0.002 g	± 0.01 g	± 0.005 g	± 0.005 g
- Fine range	-	-	-	-	-	-	-	± 0.002 g	± 0.002 g
Sensitivity drift / °C (10 ... 30 °C)	2 x 10 ⁻⁶	2 x 10 ⁻⁶	4 x 10 ⁻⁶	4 x 10 ⁻⁶	3 x 10 ⁻⁶	1.5 x 10 ⁻⁶	2 x 10 ⁻⁶	4 x 10 ⁻⁶	1.5 x 10 ⁻⁶
Stabilization time ¹⁾	2.5/4/6 s	2.5/4/6 s	1.5/2/3 s	1.5/2/3 s	1.5/2/3 s	2.5/4/6 s	9/12/15 s	1.5/2/3 s	2.5/4/6 s
Update speed	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s
Display ²⁾	FD	FD	FD	FD	FD	LCD	LCD	FD	LCD
Result deviation									
in inclined position (1:1000)	0.5 mg	0.5 mg	0.005 g	0.005 g	0.005 g	0.005 g	0.02 g	0.005 g	0.005 g
Weighing pan	Ø 80 mm	Ø 80 mm	Ø 130 mm	Ø 130 mm	Ø 130 mm	Ø 130 mm	Ø 130 mm	Ø 130 mm	Ø 130 mm
Calibration weight ³⁾	50 g/E2	100 g/E2	100 g/F1	100 g/F1	200 g/F1	1000 g/E2	5000 g/E2	100 g/F1	1000 g/F1
Net weight	6.0 kg	6.6 kg	3.8 kg	3.8 kg	3.8kg	3.8 kg	6.6 kg	3.8 kg	3.8 kg
Balance housing (W x D x H) in mm	194 x 316 x 252	194 x 316 x 337	194 x 316 x 68				194 x 316 x 337	194 x 316 x 68	
Power consumption	6 VA								
Fusing	63 mA/220 V								
	125 mA/110 V								



	PM300	PM600	PM2000	PM4000	PM6100	PM4800 DeltaRange	PM3000	PM6000	PM6
Readability	0.01 g	0.01 g	0.01 g	0.01 g	0.01 g	0.1 g	0.1 g	0.1 g	1 g
- Fine range (recallable)	-	-	-	-	-	0.01 g	-	-	-
Weighing capacity	310 g	610 g	2100 g	4100 g	6100 g	4100 g	3100 g	6100 g	6100 g
- Fine range (recallable)	-	-	-	-	-	800 g	-	-	-
Taring range (subtraktiv)	310 g	610 g	2100 g	4100 g	6100 g	4100 g	3100 g	6100 g	6100 g
Reproducibility (s)	0.003 g	0.005 g	0.005 g	0.01 g	0.01 g	0.03 g	0.03 g	0.05 g	0.3 g
- Fine range	-	-	-	-	-	0.01 g	-	-	-
Linearity	± 0.01 g	± 0.01 g	± 0.02 g	± 0.02 g	± 0.02 g	± 0.05 g	± 0.1 g	± 0.1 g	± 1 g
- Fine range	-	-	-	-	-	± 0.02 g	-	-	-
Sensitivity drift / °C (10 ... 30 °C)	4 x 10 ⁻⁶	6 x 10 ⁻⁶	4 x 10 ⁻⁶	3 x 10 ⁻⁶	3 x 10 ⁻⁶	4 x 10 ⁻⁶	4 x 10 ⁻⁶	6 x 10 ⁻⁶	6 x 10 ⁻⁶
Stabilization time ¹⁾	1/1.5/2.5 s	1.5/2/3 s	1.5/2/3 s	1.5/2/3 s	2.5/4/6 s	1.5/2/3 s	1/1.5/2.5 s	1/1.5/2.5 s	1/1.5/2.5 s
Update speed	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s	0.13 s
Display ²⁾	FD	FD	FD	FD	FD	FD	FD	FD	FD
Result deviation									
in inclined position (1:1000)	0.01 g	0.05 g	0.05 g	0.05 g	0.05 g	0.05 g	0.5 g	0.5 g	1 g
Weighing pan	Ø 130 mm	Ø 150 mm	Ø 150 mm	Ø 170 mm	Ø 150 mm	Ø 170 mm	182 x 228	182 x 228	182 x 228
Calibration weight Class F1 ³⁾	100 g	500 g	1000 g	2000 g	2 x 2000 g	1000 g	1000 g	2000 g	2000 g
Net weight	3.8 kg	3.8 kg	3.8 kg	3.8 kg	3.8 kg	3.8 kg	4.2 kg	4.2 kg	4.2 kg
Balance housing (W x D x H) in mm	194 x 316 x 68								
Power consumption	6 VA								
Fusing	63 mA/220 V								
	125 mA/110 V								

¹⁾ dependent on the setting of the vibration adapter

²⁾ FD Fluorescent display, self-luminous
LCD Liquid crystal display, passive

³⁾ for noncertified version

**To protect your METTLER TOLEDO product's future:
METTLER TOLEDO Service assures the quality, measuring accuracy and
preservation of value of all METTLER TOLEDO products for years to come.
Please send for full details about our attractive terms of service.
Thank you.**



Subject to technical changes and to the availability
of the accessories supplied with the instruments.

© Mettler-Toledo GmbH 1999 702395C Printed in Switzerland 9910/2.12

Mettler-Toledo GmbH, Laboratory & Weighing Technologies, CH-8606 Greifensee, Switzerland
Phone +41-1-944 22 11, Fax +41-1-944 30 60, Internet: <http://www.mt.com>